

PROJECT LOCATION FOR CRESCENT HARBOR CREEK RESTORATION IS ON THE WHIDBEY ISLAND NAVAL AIR STATION BETWEEN CRESCENT HARBOR ROAD AND A TIDAL ESTUARY DIRECTLY CONNECTED TO CRESCENT HARBOR (PUGET SOUND). ALL PROJECT WORK WOULD BE SOUTH OF CRESCENT HARBOR ROAD, TO RESTORE A 1/4-MILE LENGTH OF CRESENT HARBOR CREEK FROM A DITCHED ALIGNMENT TO NATURAL MEANDERING STREAM CHANNEL. MAP SCALE 1:24,0000 (USGS) 1" = 2,000'.

CRESCENT HARBOR CREEK RESTORATION

Eric Mickelson, Project Manager Skagit River System Cooperative 11426 Moorage Way (P. D. Box 368) La Conner, WA 98257

360-466-7228 office 360-441-2944 cell emickelson@skagitcoop.org


DRAWING LIST:

- 1 PROJECT LOCATION & DRAWING LIST
- 2 SITE PREPARATION & CLEARING 3 STREAM RESTORATION SITE PLAN (SOUTH)
- 4 STREAM RESTORATION SITE PLAN (NORTH)
- CHANNEL CROSS-SECTIONS 0+00 TO 6+00
- 6 CHANNEL CROSS-SECTIONS 7+00 TO 13+00
- 7 SUBGRADE SECTIONS & TYPICAL CHANNELS
- 8 EROSION CONTROL FOR NEW CHANNEL BANKS
- 9 DESTINATIONS FOR EXCAVATED MATERIALS
- 10 CHANNEL CONSTRUCTION DATA
- 11 CREEK DE-WATERING & FISH RECOVERY
- 12 ROUGHENED CHANNEL SITE PLAN
- 3 ROUGHENED CHANNEL PROFILE & DETAILS

Notes for Potential Backwater Upstream of Existing Culvert

The project engineer completed a detailed survey near the existing culvert and prepared rating curves to quantitatively show the relationship between creek flow in cubic feet per second (cfs) and estimated water surface elevations at the downstream end existing culvert. The specific interest was whether or not the proposed channel would result in additional backwater of the existing culvert. Flow rating curves are shown in Figure 1, with all rating curves adjusted per creek alignment to hydraulically coincide with the downstream end of the existing culvert. Conclusions from the analysis of rating curves:

- > On the chart (Figure 1), rating curves to the right represent channels that have higher flow capacity than curves to the left.
- For flows zero to 40 cfs, the existing culvert and downstream channel would both have slightly more flow capacity than a roughened channel at 3% slope; see the thick solid line (proposed channel) to the left of dashed lines (existing conditions) in Figure 1. Within this flow range, the proposed roughened channel would create a minor backwater within the existing culvert, up to about 0.3' deep. Slightly higher water elevations (up to 0.3' higher) upstream within this flow range were not considered any concern.
- Above 40 cfs flow in Crescent Harbor Creek to the estimated 100-year flood flow and above, the proposed roughened channel would have increasingly high flow conveyance capacity compared with existing conditions. On-site, beginning at about 60 cfs flow, there would be a small water level drop from the existing culvert into the roughened channel. This water level drop would be about 0.5'-high at the estimated 100-year flood flow; there would not be any upstream backwaters at high creek levels, or during floods.




JANUARY 2021





PROJECT LOCATION IS
NEAR THE EASTERN EDGE
OF DAK HARBOR, WASHINGTON


CRESCENT HARBOR CREEK RESTORATION SKAGIT RIVER SYSTEM COOPERATIVE


PROJECT LOCATION & DRAWING LIST DRAWING 1















TYPICAL SUBGRADE w/ SCISSOR LOG WEIR AT UPSTREAM END POOL





TYPICAL SUBGRADE w/ LOG CONSTRICTION AT UPSTREAM END POOL


Channel Subgrade, Large Wood & Cobble/Gravel/Sand Mix Notes:

- Typical channel dimensions shown this drawing. Actual dimensions will vary along the restored channel length, within the limits shown.
- 2. Low flow riffle widths 4' to 10'-wide w/ variable bank slopes.
- 3. Pools 2' to 4'-deep by 10' to 20'-wide w/ variable bank slopes.
- All logs and logs w/ rootwads to be salvaged from Crescent Harbor Creek estuary at low tide. Select logs 12"-24" trunk diameter (+/-) approx. 15'-25' long.
- 5. All logs extending into channel shall have broken ends (no sawn ends). Buried log ends may by sawn or broken.
- Cobble/Gravel/Sand to contain the four materials listed below, each at ¼ of the mix by volume:

Rounded cobbles 6" to 18"-size. Gravel 2" to 6"-size Gravel 1" to 2"-size. Washed sand. (these size ranges may vary slightly)








CRESCENT HARBOR CREEK RESTORATION

SUBGRADE SECTIONS & TYPICAL CHANNELS

SKAGIT RIVER SYSTEM COOPERATIVE

DRAWING 7



Erosion Control Requirements for Crescent Harbor Creek Restoration:

- 1. Fill of Existing Creek Channel (ditch) and Abandoned Agricultural Ditches All specified locations (Drawing 9) to be filled to surrounding ground levels, using native soils excavated for new creek channel alignment. Lightly tamp fill into ditches, but do not compact, rake surface with excavator teeth for rough ground surface. Then, spread erosion-control seeds with seed variety and application rate determined by SRSC, and spread weed-free straw at an application rate of 1 bale per 500 ft² area.
- 2. New Creek Channel Banks (all including roughened channel) Erosion control for streambanks will be erosion-control seeds spread over all areas between undisturbed ground and cobble, gravel, or rock (streambed materials), planting native shrubs and trees, and then placement of jute matting over all channel bank areas.
- 3. **Surplus Soil Disposal Area** The upland area covered with surplus excavated materials shall be gradually sloped to match adjacent terrain, with the soil surfaces raked. Then, spread erosion-control seeds with seed variety and application rate determined by SRSC, and spread weed-free straw at an application rate of 1 bale per 500 ft² area.



Notes for Native Plants:

10 FEET

SCALE: 1'' = 5'

Native trees shall be 18" to 4'-high; willows shall be 1' to 2'-high. Space trees 15' apart along both channel banks, stagger up-and-down banks, and alternate tree species. Place trees about 20' apart for fill over existing creek channel (ditch); stagger spacing and species. Plant 20 trees at disposal site for surplus soil. Place all willows near water edge in new creek channel, with random pattern averaging one willow per 10' channel length.


\triangleright	Shore Pine	90 each
Þ	Sitka Spruce	80
Þ	Grand Fir	80
Þ	Pacific Willow	130

JANUARY 2021

CRESCENT HARBOR CREEK RESTORATION SKAGIT RIVER SYSTEM COOPERATIVE

EROSION CONTROL FOR NEW CHANNEL BANKS





Crescent Harbor Creek Restoration

Log & Root	Log & Rootwad Placement Schedule	Log & Rootwad Placement Schedule Sui	Selli nai boi noa	Subgrade Slope & Elevation, Riffle & Pool Designation and Data	& Elevation, F	Riffle & Pool	Designation a	nd Data
Cumulative Distance					Cumulative	Subgrade		Wood at
from Estuary (ft)	Log or Rootwad	Streambank	Reach Length (ft)	Reach Slope	from Estuary (ft)	Elevation (ft)	Reach Type	Upstream End
20	gol	west	0	0.00	0	7.1	riffle	
20	log	east	40	0.01	40	7.5	riffle	
06	gol	west	2	-0.60	45	4.5	lood	
110	rootwad	west	10	0.00	55	4.5	lood	-
120	801	West	0 40	0.00	100	C.7	riffle	scissor log weil
190	90	east	40	0.02	140	8.7	riffle	
220	log	east	2	-0.40	145	6.7	lood	
240	gol	west	10	0.00	155	6.7	lood	
270	log	east	2	0.40	160	8.7	lood	scissor log weir
290	log	west	20	0.01	180	8.9	riffle	
330	log	west	30	0.01	210	9.2	riffle	
360	log	west	40	0.01	250	9.6	riffle	
400	gol	east	40	0.01	290	10.0	riffle	
420	rootwad	west	2	-0.40	295	8.0	lood	
450	go]	west	10	0.00	305	8.0	- 00d	
470	gol .	west	5	0.40	310	10.0	lood	log constriction
200	gol .	west	30	0.01	340	10.3	riffle	
520	gol .	east	30	0.03	370	11.2	riffle	
560	gol .	west	20	0.01	390	11.4	rittle	
230	gol 2	west	30	0.01	420	11.7	rifflo	
020	80	east	}	0.02	465	8.5	000	
069	gol gol	west	10	0.00	475	8.5	lood	
730	80	east	2	0.80	480	12.5	lood	scissor log weir
760	log	east	40	0.02	520	13.3	riffle	
780	log	west	30	0.01	550	13.6	riffle	
810	log	west	3	-0.60	555	10.6	lood	
830	rootwad	west	10	00:00	292	10.6	lood	
098	log	east	2	09:0	570	13.6	lood	scissor log weir
068	gol	west	20	0.01	590	13.8	riffle	
910	log	east	40	0.02	630	14.6	riffle	
950	go .	east	5	-0.60	635	11.6	lood	
0/6	Bol	West	3 4	0.00	040	17.6	1000	acitairtage pol
1020	Lociwad	east	ر د	0.00	680	14.9	riffle	108 collection 901
1060	gol gol	west	40	0.02	720	15.7	riffle	-
1080	90 80	east	2	-0.80	725	11.7	lood	
1110	log	east	10	00.00	735	11.7	lood	
1130	gol	west	2	08.0	740	15.7	lood	scissor log weir
1160	log	west	20	0.01	760	15.9	riffle	
1200	gol .	west	20	0.02	780	16.3	riffle	
1230	gol .	east	۲ ر	-0.40	/85	14.3	lood .	
1260	gol	east	10	0.00	795	14.3	lood	1
1280	gol	east	5 5	0.40	800	16.3	lood	log constriction
1320	gol	east	30	0.01	058	16.6	rifflo	
1390	rootwad	east	OS I	0.01	000	14.0	1000	
1400	roughen	roughened channel	- OI	0.00	875	14.9	000	
1420	roughen	roughened channel	2 2	0.40	880	16.9	lood	log constriction
				100	000	, ,	- 155.	



Notes to Incorporate Data into Construction:

1. Engineer will determine channel centerline alignment on-site.

- 2. Engineer will set clearing limits at 50' on-center for clearing.
- Engineer will survey and measure real-time as construction work proceeds in upstream direction. On-site references will be provided to contractor including subgrade elevations and slope, pool or riffle, streambank slopes, log and rootwad placement.

JANUARY 2021

CRESCENT HARBOR CREEK RESTORATION SKAGIT RIVER SYSTEM COOPERATIVE

CHANNEL CONSTRUCTION DATA DRAWING 10

Creek De-Watering & Fish Recovery Notes: 1. The new creek channel (see site plan Drawings 3 and 4) shall be completed prior to start of roughened channel construction, from existing estuary (Station 0+00) to approximately Station 13+50 (east edge existing channel near Crescent Harbor Road). Construction of the roughened channel will require bypass of all creek flow into the new channel, with requirements as listed below. 2. "First flush" of creek flow (via pumps) down new channel alignment will be turbid. Water infiltration as flow proceeds down the channel, and settling of silt in pools will substantially reduce sediment conveyance to the estuary, but turbid water is still expected to reach the estuary. Contractor to have generator and two 2"-dia. submersible pumps staged at downstream end new channel to intercept muddy water just upstream of estuary. As needed, pump muddy water to upland flat area for infiltration into ground, until flowing water has INSTALL SANDBAG DAM INvisibility greater than 12". Then, allow all freshwater to flow directly into estuary. EXISTING CULVERT TO FORM SRSC staff to be on-site during creek bypass operations before start of roughened channel construction. SHALLOW PUMPING POOL Prior to Contractor pumping of flow from Crescent Harbor Creek into new channel alignment, SRSC staff will isolate the project reach using block nets and will exclude fish from the project area using accepted protocols (USFWS 2012). After flow bypass starts, SRSC staff will repeatedly walk the existing creek channel (aka ditch) as water levels slowly recede to rescue observed fish; fish recovery will be done over the entire de-watered channel length to estuary. Contractor to place sandbag dam within existing culvert to form a small pumping pool, then supply and operate pump(s) for continuous (including overnight) flow bypass around the roughened channel construction area. Flow discharge from pump(s) will be about 100' downstream of the existing culvert. After start of bypass flow. Contractor to monitor downstream advance of flow in new creek channel to determine THICK LINES SHOW LIMITS FORwhen pumping of muddy water near estuary required. 12" TO 24"-SIZE BOULDERS FOR ROUGHENED CHANNEL 5. With flow bypass established, Contractor to provide a separate gas-powered trashpump to de-water pool below existing culvert, with SRSC staff on-hand for fish removal and rescue. Contractor to operate pump to slowly draw down pool water level, in combination with SRSC net operations for safe fish removal. Fish to be re-located to new creek channel near upstream end, which will have relatively clear water. ORDINARY HIGH WATER-6. Engineer has observed good success with flow bypass (of the expected low flow rate late summer) using FOR DITCHED ALIGNMENT one or two 2"-diameter submersible electric pumps powered with a small gas-powered generator. EXISTING-**CUL VERT** FLOW BYPASS PIPE(S) BUILD ROUGHENED CHANNEL DURING FLOW BYPASS DISCHARGE CREEK FLOW INTO NEW CHANNEL COMPLETE NEW CREEK CHANNEL CONSTRUCTION DURING FLOW BYPASS JANUARY 2021 CRESCENT HARBOR CREEK RESTORATION COMPLETE NEW CREEK CHANNEL SKAGIT RIVER SYSTEM COOPERATIVE CONSTRUCTION TO THIS POINT PRIOR TO FLOW BYPASS & CREEK DE-WATERING & FISH RECOVERY ROUGHENED CHANNEL WORK 10 FEET DRAWING 11 SCALE: 1" = 5'

