

WHIDBEY ISLAND-FRONTAL SARATOGA PASSAGE (171100190103), 01/23/23

Current Status: Accepted

Inspection Details

Inspection Type: Final	Inspected By: Bridget.Kaminski
Inspection Method: Field Review	Inspection Date & Time: 01/23/23 11:00 AM
Data Sources: The resources I used to conduct the inspection included, PRISM attachments, Google maps, sponsor website or Skagit county website.	Inspection Reference #: 3469
Compliance Area: Whidbey Island-Frontal Saratoga Passage (171100190103)	Inspection Note: The only participants for this site visit were me and Matt Etinger. We used the driveway to a logging company, stayed left and parked in an open area.

Worksites Inspected

Skagit River System Cooperative

Project # Proj Type	Project Name WorkSite Name	Status	Primary Pgm
18-1366 Rest	Crescent Harbor Creek Restoration #1 Lower Crescent Harbor Creek	Active	SALMON ST PROJ

Sponsor Contacts

Skagit River System Cooperative

Person Name	Project Role	Phone Number	Email Address
Brenda Ibarra Skagit River Sys Cooperative	Billing	(360) 466-7370	bibarra@skagitcoop.org
Clea Barenburg Island County LE	Lead Entity Contact	(360) 544-2272	C.Barenburg@islandcountywa.gov
Devin Smith Skagit River Sys Cooperative	Project Contact	(360) 391-1984	dsmith@skagitcoop.org
Eric Mickelson Skagit River Sys Cooperative	Alt Project Contact	(360) 770-5312	emickelson@skagitcoop.org
Sabrina Subia Rec. and Conserv. Office	MAgy Fiscal Contact	(360) 725-3938	Sabrina.Subia@rco.wa.gov

Questions

Salmon Restoration projects

#1: Was the project implemented as designed and scoped?

Yes.

Acquisition and Restoration Projects

#1: If funding acknowledgement signs are required, are they installed?

Yes.

#2: Site Visit Summary

Inspection complete. On January 23, 2023, I performed a site visit with Clea Barenburg (LE Coordinator), Eric Mickelson (Sponsor), and a representative from the Navy (landowner). We walked the reconfigured stream from the Culvert to the estuary. The culvert did not get replaced as there was no need with the newly roughened streambed. The stream did appear natural with meanders, pools, instream wood, and mixture of streambed materials (cobble, gravel, mud, rocks). The Sponsor indicated that Chinook have been spotted in this stretch of the stream. New riparian planting on each side of the stream were apparent.

#3: Are there any observable concerns regarding this project that should be noted? If yes, please describe:

No.

#4: Is this project being monitored by a statewide, IMW, or other effectiveness monitoring program? If yes, please describe:

No.

Attachments

ALL PHOTOS AND FILES

Attachment Type	Title	File Name	User, Attach Date
Inspection Photos	18-1366 Crescent	18-1366 Crescent Harbor Cr. Rest	BridgetK, 02/17/2023
	Harbor Cr. Rest	pics.pptx	
	pics.pptx		

Issues/Tasks From This Inspection

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
---	------------------	------	---------	--------	----------	---------------	---------

Other Open Issues/Tasks

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
---	------------------	------	---------	--------	----------	---------------	---------