


6  
5  
1/4 CORNER



LINE	BEARING	DISTANCE
11	N 70.5921° E	74.52
12	N 33.4956° E	35.20
13	N 53.4656° E	74.20
14	N 57.0060° E	725.08
15	N 44.5312° E	45.60
16	N 20.0657° E	6.30
17	S 50.1956° E	25.66
18	N 62.6624° E	57.57
19	N 48.5110° E	41.80
20	N 48.3106° E	41.80
21	N 57.1055° W	82.47
22	N 48.0134° E	107.32
23	N 30.5533° W	122.21
24	N 45.4619° E	84.85
25	N 08.7180° E	78.29
26	N 11.2518° E	83.82
27	N 11.4397° E	122.06
28	N 17.1530° E	99.07
29	N 17.2121° E	92.87
30	N 26.9566° E	80.65
31	N 22.9910° E	90.59
32	N 23.9934° E	74.46
33	N 32.9238° E	98.04
34	N 42.0636° E	110.81
35	N 48.7111° E	125.84
36	N 54.2593° E	48.88
37	S 88.1036° E	14.33
38	N 48.4231° E	69.33
39	N 33.9302° E	20.84
40	N 22.5527° E	11.78
41	N 47.0823° E	77.74
42	N 29.2407° E	52.69
43	N 21.5136° E	87.40
44	S 70.1329° E	38.43
45	S 45.4612° E	10.09
46	N 22.9939° E	300.00
47	N 22.7104° E	152.00
48	N 27.1016° E	305.00
49	N 22.9226° E	73.79
50	N 52.4659° E	71.32

## LEGEND

● : DENOTES 1/2" REBAR WITH "ESI 27327"  
CAP SET THIS SURVEY

○ : DENOTES FOUND POINT AS DESCRIBED

( ) : DENOTES DISTANCE OR BEARING  
RELATIONSHIP OF RECORD

ROS : REFERENCE TO ISLAND COUNTRY

RECORDED SURVEY  
AEN : BEEFERENCE TO ISLAND COUNTY

AUDITOR'S FILE NUMBER

## FOUND POINT DESCRIPTIONS

- ① FOUND 1/2" REBAR WITH LEONARD 8992 CAP (ACCEPTED AND HELD)
- ② FOUND 1/2" REBAR WITH SKODGE LS 19645 CAP N 0.05 OF LINE
- ③ FOUND 1/2" REBAR WITH SKODGE LS 19649 CAP ON LINE
- ④ FOUND 1/2" REBAR WITH ALLEGRAE CAP N TREE ROOT N 0.12 OF LINE
- ⑤ FOUND 1/4" INSIDE DIAMETER IRON PIPE S 1.11 E 6.27 OF CALCULATED CORNER
- ⑥ FOUND 8" OUSTE REBAR WITH LS 12716 CAP S 0.56 E 0.32 OF CALCULATED CORNER
- ⑦ FOUND 1" INSIDE DIAMETER RUSTED IRON PIPE WITH WOOD PLUG EXPOSED 1.0' LEANING SLIGHTLY SOUTH E 4.37 OF LINE
- ⑧ FOUND 1" INSIDE DIAMETER OPEN IRON PIPE EXPOSED 0.9' LEANING SLIGHTLY SOUTH E 3.65 OF LINE
- ⑨ FOUND 1" INSIDE DIAMETER OPEN IRON PIPE EXPOSED 0.4' E 0.38 OF LINE
- ⑩ FOUND 1/2" REBAR WITH LEONARD 8992 CAP LEANING SLIGHTLY NORTH W 0.05 OF LINE
- ⑪ FOUND 1/2" REBAR WITH LEONARD 8992 CAP ON LINE
- ⑫ FOUND 1/2" REBAR WITH LEONARD 8992 CAP LEANING SLIGHTLY NORTH W 0.05 OF LINE
- ⑬ FOUND 1/2" REBAR WITH LEONARD 8992 W 0.03 OF LINE
- ⑭ FOUND 1/2" REBAR WITH LEONARD 8992 CAP W 0.10 OF LINE
- ⑮ FOUND 1/2" REBAR WITH LEONARD 8992 CAP APPEARS TO HAVE BEEN KNOCKED OVER
- ⑯ FOUND 1/2" REBAR WITH LEONARD 8992 CAP W 0.13 OF LINE
- ⑰ FOUND 1/2" REBAR WITH ALLEGRAE CAP AT TOP OF BLUFF W 0.05 OF LINE
- ⑱ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 1.50 OF E RIGHT-OF-WAY LINE
- ⑲ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 1.150 OF E RIGHT-OF-WAY LINE
- ⑳ FOUND 1/2" REBAR WITH +12716 CAP E 10.61 OF E RIGHT-OF-WAY LINE
- ㉑ FOUND 1/2" REBAR WITH +12716 CAP E 10.61 OF E RIGHT-OF-WAY LINE
- ㉒ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉓ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉔ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉕ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉖ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉗ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉘ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉙ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉚ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉛ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉜ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉝ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉞ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㉟ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊱ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊲ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊳ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊴ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊵ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊶ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊷ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊸ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊹ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊺ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊻ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊼ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊽ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊾ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE
- ㊿ FOUND 1/2" REBAR WITH ALLEGRAE CAP E 11.50 OF E RIGHT-OF-WAY LINE

# AUDITOR'S CERTIFICATE

FILED FOR RECORD THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 2012, AT \_\_\_\_\_ M.  
IN BOOK \_\_\_\_\_ OF SURVEYS AT PAGE \_\_\_\_\_, AT THE REQUEST OF HARMSEN AND ASSOCIATES, INC.

ISLAND COUNTY AUDITOR BY DEPUTY

AUDITOR'S FILE NO.

## SURVEY FOR

# THE NATURE CONSERVANCY

A PORTION OF GOVERNMENT LOT 1 OF SECTION 5 T2WN 31N R6E 3E WM  
AND

GOVERNMENT LOT 1 OF SECTION 8 T2N 31N R3E 3E WM

SCALE: 1" = 20'  
DRAWN BY: JAC  
MAY 30, 2012



**HARMSEN**  
& ASSOCIATES INC.

JOB#: 12-031  
F/B: MV - 90  
SHEET: 1 OF 1