




FIGURE 13 – Change in Channel Width From 1944 to 2013




FIGURE 14 – Pool Locations and Types

Gold Creek Habitat Assessment & Conceptual Design



Gold Creek Habitat Assessment and Conceptual Design
Current Bank Condition Map

Topographic data source: 1999 USGS NED (10-meter); 2012 LIDAR (Watershed Sciences)
Aerial photo data source: 2013 NAIP

0 500 1,000 1,500 2,000 Feet
Lambert conformal conic projection, NAD 1983
State Plane Coordinate System (WA South Zone)

NATITAS
CONSERVATION
TRUST

Natural Systems Design

FIGURE 15 – Current Bank Condition

Gold Creek Habitat Assessment & Conceptual Design

Natural Systems Design

P.O. Box 15609
Seattle, WA 98115