

NASON RIDGE TRAIL, 10/29/18

Current Status: Accepted

Inspection Details

Inspection Type: Final
Inspected By: MarcD
Inspection Method: Desk & Field Review
Inspection Date & Time: 10/29/18
Data Sources:
Inspection Reference #: 1542
Compliance Area: Nason Ridge Trail
Inspection Note:

Worksites Inspected

Chelan County

Project # Proj Type	Project Name WorkSite Name	Status	Primary Pgm
15-1210	Upper White Pine Floodplain Reconnection	Active	SALMON ST PROJ
Rest	#1 Nason Creek Upper White Pine		

Sponsor Contacts

Chelan County

Person Name	Project Role	Phone Number	Email Address
Jennifer Hadersberger Chelan County of	Project Contact	(509) 667-6682	Jennifer.hadersberger@CO.CHELAN.WA.US
Pete Teigen Upper Columbia Sal Rec BD LE	Lead Entity Contact	(509) 662-4710	pete.teigen@ucsr.org
Sandra Scott Rec. and Conserv. Office	MAgy Fiscal Contact	(360) 902-3007	Sandy.Scott@rco.wa.gov
Sofia Bjorklund Chelan Co Natural Resource	Billing	(509) 667-6324	sofia.bjorklund@co.chelan.wa.us

Questions

Salmon Restoration projects

#1: Was the project implemented as designed and scoped?

Yes. Interfluv designed a great project.

Acquisition and Restoration Projects

#1: If funding acknowledgement signs are required, are they installed?

No.

#2: Site Visit Summary

Inspection complete. Project looks great. Should present to SRFB at future meeting. Interfluv and Chelan County NRD did an outstanding job on this complicated project. Moved Chelan PUD powerlines, removed a levee, and filled in old channel against BNSF railroad line. See photos.

#3: Are there any observable concerns regarding this project that should be noted? If yes, please describe:

No.

#4: Is this project being monitored by a statewide, IMW, or other effectiveness monitoring program? If yes, please describe:

No.

Attachments

PHOTOS (JPG, GIF)



ALL PHOTOS AND FILES

Attachment Type	Title	File Name	User, Attach Date
Photo	10-29-18 Final Inspection	P1130789.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 12	P1130859.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 13	P1130862.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 10	P1130840.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 15	P1130867.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 6	P1130815.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 4	P1130805.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 9	P1130831.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 7	P1130817.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 5	P1130812.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 2	P1130797.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 3	P1130801.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 1	P1130792.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 14	P1130865.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 11	P1130847.jpg	MarcD, 11/09/2018
Photo	10-29-18 Final Inspection 8	P1130822.jpg	MarcD, 11/09/2018

Issues/Tasks From This Inspection

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
---	------------------	------	---------	--------	----------	---------------	---------

Other Open Issues/Tasks

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
---	------------------	------	---------	--------	----------	---------------	---------