

Inspection Report

MIDDLE SAMMAMISH RIVER, 02/21/19

Current Status: Accepted

Inspection Details

Inspection Type: Final Inspected By: EButler

Inspection Method: Field Review Inspection Date & Time: 02/21/19 09:30 AM

Data Sources: Inspection Reference #: 1736

Compliance Area: MIDDLE SAMMAMISH RIVER Inspection Note: Cold February morning. Snow still on the ground made

it easy to see the creek.

Worksites Inspected

King County

Project # Proj Type	Project Name WorkSite Name	Status	Primary Pgm
15-1058	Lower Bear Creek Natural Area Additions	Active	PSAR
Acq	#1 Lower Bear Creek		

Sponsor Contacts

King County

Person Name	Project Role	Phone Number	Email Address
Janne Kaje King County of	Alt Project Contact	(206) 477-4078	janne.kaje@kingcounty.gov
Jason Wilkinson WRIA 8 LE (King County)	Lead Entity Contact	(206) 477-4786	jason.wilkinson@kingcounty.gov
Sandra Scott Rec. and Conserv. Office	MAgy Fiscal Contact	(360) 902-3007	Sandy.Scott@rco.wa.gov
Suzanna Smith WRIA 9 LE (King County)	Regional Contact	(206) 477-4641	susmith@kingcounty.gov
Tom Beavers King Co Water & Land Res	Project Contact	(206) 477-4743	tom.beavers@kingcounty.gov
Veronica Doherty King County DNR & Parks	Billing	(206) 477-3515	veronica.doherty@kingcounty.gov

Questions

Acquisition and Restoration Projects

#1: If funding acknowledgement signs are required, are they installed?

Yes.

#2: Site Visit Summary

Inspection complete. The acquisition targeted a portion of the property owned by the Little Bit Riding Center with the Lower Bear Creek running through it. The County has initiated noxious weed treatment, and are preparing for a future floodplain reconnection and riparian restoration project in 2020. The property is located in a developed watershed, but offers important spawning and rearing habitat for salmonids.

#3: Are there any observable concerns regarding this project that should be noted? If yes, please describe:

No

#4: Is this project being monitored by a statewide, IMW, or other effectiveness monitoring program? If yes, please describe:

No.

Attachments

PHOTOS (JPG, GIF)



ALL PHOTOS AND FILES

Attachment Type	Title	File Name	User, Attach Date
Photo	IMG_0002.JPG	IMG_0002.jpg	ElizabethB, 03/14/2019
Photo	IMG_0014.JPG	IMG_0014.jpg	ElizabethB, 03/14/2019
Photo	IMG_0015.JPG	IMG_0015.jpg	ElizabethB, 03/14/2019

Issues/Tasks From This Inspection

Туре

SubType

Issue/Task Title

Other Open Issues/Tasks							
#	Issue/Task Title	Туре	SubType	Status	Assigned	Relationships	Sponsor
265	agricutlural use of living estate area	Compliance Issue	Conversion	Open	JoshL	#1181: MIDDLE SAMMAMISH RIVER, 9/14/17, 99-1705 Acq, Compliance, JoshL, Snohomish County of INSPECTION	Snohomish County
266	Parking expansion eligibility review	Use Request	Allowable use request	Open	JoshL	#1181: MIDDLE SAMMAMISH RIVER, 9/14/17, 99-1705 Acq, Compliance, JoshL, Snohomish County of INSPECTION	Snohomish County

Status

Assigned

Relationships

Sponsor