

MIDDLE SAMMAMISH RIVER, 07/02/21

Current Status: Accepted

Inspection Details

Inspection Type: Final	Inspected By: EButler
Inspection Method: Field Review	Inspection Date & Time: 07/02/21 06:30 PM
Data Sources:	Inspection Reference #: 2828
Compliance Area: MIDDLE SAMMAMISH RIVER	Inspection Note: Site looks good. High heat over past few days may have stressed a few of the conifers. Let Proj Manager know to water.

Worksites Inspected

Adopt A Stream Foundation

Project # Proj Type	Project Name WorkSite Name	Status	Primary Pgm
16-1215 Rest	Bear Creek Reach 6 - Phase II Construction #1 Friendly Village Phase II worksite (downstream of	Active	PSAR

Sponsor Contacts

Adopt A Stream Foundation

Person Name	Project Role	Phone Number	Email Address
Jason Wilkinson WRIA 8 LE	Lead Entity Contact	(206) 477-4786	jason.wilkinson@kingcounty.gov
Jim Lochner Rec. and Conserv. Office	MAgy Fiscal Contact	(360) 902-3007	Jim.Lochner@rco.wa.gov
Suzanna Smith WRIA 9 LE	Regional Contact	(206) 477-4641	susmith@kingcounty.gov
Tom Murdoch Adopt A Stream Foundation	Agreement	(425) 316-8592	tomm@streamkeeper.org
Walter Rung Adopt A Stream Foundation	Project Contact	(425) 316-8592 111	walterr@streamkeeper.org

Questions

Salmon Restoration projects

#1: Was the project implemented as designed and scoped?

Yes.

Acquisition and Restoration Projects

#1: If funding acknowledgement signs are required, are they installed?

Yes. Sign installed. See photo attached to PRISM Project.

#2: Site Visit Summary

Inspection complete. Instream jog jams look like they've functioned well over the winter high flows. Riparian plantings are well spaced and appear in good shape, with a couple exceptions of conifers that may need water.

#3: Are there any observable concerns regarding this project that should be noted? If yes, please describe:

No. We had record heat over the weekend, and looks like some of the riparian plantings may be stressed. Asked for clarification on watering plans and whether plants that do not survive will be replaced..

Sponsor provided stewardship plan for riparian habitat, attached in PRISM.

#4: Is this project being monitored by a statewide, IMW, or other effectiveness monitoring program? If yes, please describe:

No.

Attachments

PHOTOS (JPG, GIF)



ALL PHOTOS AND FILES

Attachment Type	Title	File Name	User, Attach Date
Photo	IMG_0775.JPG	IMG_0775.jpg	ElizabethB, 06/29/2021
Photo	IMG_0769.JPG	IMG_0769.jpg	ElizabethB, 06/29/2021
Inspection Photos	2021.07.02 16-1215 Final	2021.07.02 16-1215 Final Inspection	ElizabethB, 08/13/2021
	Inspection	Visit.pptx.pptx	
	Visit.pptx.PPTX		

Issues/Tasks From This Inspection

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
---	------------------	------	---------	--------	----------	---------------	---------

Other Open Issues/Tasks

#	Issue/Task Title	Type	SubType	Status	Assigned	Relationships	Sponsor
266	Parking expansion eligibility review	Use Request	Allowable use request	Open	JoshL	#1181: MIDDLE SAMMAMISH RIVER, 9/14/17, 99-1705 Acq. Compliance, JoshL, Snohomish County of INSPECTION	Snohomish County